
ASSEMBLY INSTRUCTIONS FOR#133638



IMPORTANT

TURN OFF THE POWER AT THE MAIN FUSE OR CIRCUIT BREAKER BOX BEFORE STARTING INSTALLATION

CAREFULLY UNPACK AND IDENTIFY ALL PARTS BEFORE ASSEMBLY. BULBS ARE NOT INCLUDED

THIS INSTALLATION REQUIRES TWO PEOPLE

THIS FIXTURE WEIGHS OVER 50 LBS.

NEC:314.27B, A luminaire that weighs more then 23kg (50lb) shall be supported independently of the outlet box unless the outlet box is listed AND MARKED for the MAXIMUM weight supported.

- 1.) ATTACH HEAVY CROSS BAR (B) TO SECURE LOCATION WITH FASTENERS (A) PROVIDED BY OTHERS.
- 2.) SCREW NIPPLE (C) INTO HEAVY CROSSBAR (B). SCREW LOOP (D) ONTO NIPPLE (C).
- 3) CONNECT QUICKLINK (G) TO LOOP (D), SECURE CHAIN (G) INTO QUICKLINK THEN CLOSE SECURELY.
- 4) CONNECT QUICKLINK (J) TO BOTTOM END OF CHAIN (H).
- 5) SLIDE CANOPY (E) AND THEN NUT (F) ONTO CHAIN ASSEMBLY.
- 6) LIFT FIXTURE INTO PLACE AND SECURE LOOP (L) AT TOP OF FIXTURE ONTO QUICKLINK (J).
- 7) THREAD WIRE (K) FROM TOP OF FIXTURE THROUGH CHAIN (G), THROUGH CENTER OF NUT & CANOPY AND THROUGH CENTER OF NIPPLE (C) TO TOP OF CROSSBAR (B).
- 8) WIRE AS PER LOCAL ELECTRICAL CODES.
- 9) SLIDE CANOPY (E) OVER LOOP (D) AND SECURE IN PLACE WITH NUT (F).
- 9) FASTEN SATELLITE CANOPIES TO SECURE LOCATIONS, ON CEILING IN SIMILAR FASHION, USING LIGHT CROSS BARS PROVIDED, WITH FASTENERS PROVIDED BY OTHERS.



"A Commitment to Excellence in Lighting and Service"

CALL OUR CUSTOMER SERVICE DEPARTMENT AT 1-800-222-4009 MONDAY - FRIDAY 8:00a.m - 6:00p.m ET visit us on the web at www.mevda.com