INSTALLATION INSTRUCTIONS

FOR ITEM 258690 Greenbriar Oak Inverted Pendant



CAUTION: FAILURE TO INSTALL THIS FIXTURE PROPERLY MAY RESULT IN SERIOUS PERSONAL INJURY OR DEATH AND PROPERTY DAMAGE. We recommend installation by a licensed electrician.

This product must be installed in accordance with applicable installation code(s), by a person familiar with the construction and operation of the product and the hazards involved.*

Caution: Do not exceed maximum wattage noted on fixture. Use only recommended bulbs with fixture.

FIXTURE COMPONENTS

- 1. CANOPY ASSEMBLY
- 2. 36" CHAIN
- 3. PENDANT HARDWARE
- 4. ARM (QTY 4)
- 5. STAINED GLASS SHADE

Caution:

Be sure power is off at the main breaker box prior to installation. Read all instructions in their entirety before beginning installation.

- 1. Carefully unpack all components and make certain that everything is accounted for.
- 2. Remove Collar from Canopy Assembly to release Crossbar with Loop.
- 3. Affix Crossbar to J-Box ensuring that connection is suitable to hold a minimum of 35lbs and that Electrical Supply Wires remain accessible.
- 4. Attach desired length of Chain to Hub Quick Link at top of Pendant Hardware.
- 5. Weave Fixture Lead Wires through every 5th Link of Chain.
- 6. Slide Collar and Canopy over Lead Wires and Chain and allow them to rest on Hub.
- 7. Hang Pendant Hardware by connecting loose end of Chain to Quick Link on Crossbar Loop.
- 8. Feed Lead Wires through Crossbar Loop and Following All Local Codes and Procedures, make Electrical Connection from Lead Wires to Supply Wires.
- 9. Slide Canopy up to ceiling and secure by threading Collar onto Crossbar Loop.
- 10. Hang Arms from Hub Loops.
- 11. Hang Stained Glass Shade from loose ends of Arms.
- 12. Feed Threaded from bottom of Light Cluster through center of Stained Glass Shade. Secure with Finial.
- 13. Install 6-E26 60Watt Bulbs(not included) into Sockets.
- 14. Power on and ENJOY!!!



