



ASSEMBLY INSTRUCTIONS FOR (QGL4CHC-)



A-2902	6 HOLE BRASS CEN	1
A-4138	2 PIECE CENTER B	2
A-29	STAMPED BRASS GA	2
A-3122	2 1/4" BRASS BEL	2
A-4028	BRASS BENT ARM	4
A-4444	GAS-ELECTRIC BRA	2
A-3922	FIXED BRASS GASC	2
A-4126	ACANTHUS BRASS A	4
A-749	BRASS BEADED NOZ	4
T34	INCHES OF 3/4" R	16
A-791	BRASS BEEHIVE SL	1
A-2759	UNIVERSAL CIRCLE	1
A-3123	BRASS BALL 3/4"	1
8/32 BR SCRW	8/-32X3/8" BRASS	12
A-3003	3/4" ROUND BRASS	2
A-1156	3/4"W BRASS DONU	1
L	ASSEMBLY LABOR	240



IMPORTANT

TURN OFF THE POWER AT THE
MAIN FUSE OR CIRCUIT BREAKER
BOX BEFORE
STARTING INSTALLATION

CAREFULLY UNPACK AND IDENTIFY ALL
PARTS BEFORE ASSEMBLY. BULBS ARE
NOT INCLUDED

1. Loosen set screw and slide canopy as far up tube/neck as possible.
2. Attach crossbar to J-BOX using screws provided.
3. Wire scone to J-BOX per local electrical code.
4. Slide canopy back down tube/neck over crossbar tightly against ceiling. Secure by tightening set screw.
5. Turn power on to J-Box



"A Commitment to Excellence in Lighting and Service"

CALL OUR CUSTOMER SERVICE DEPARTMENT AT 1-800-222-4009

MONDAY - FRIDAY 8:00 a.m. - 6:00 p.m. ET

visit us on the web at www.meyda.com