


ASSEMBLY INSTRUCTIONS FOR #69053 (SBE1-1-CW57)



IMPORTANT

TURN OFF THE POWER AT THE MAIN FUSE OR CIRCUIT BREAKER BOX BEFORE STARTING INSTALLATION

CAREFULLY UNPACK AND IDENTIFY ALL PARTS BEFORE ASSEMBLY. BULBS ARE NOT INCLUDED

1. Screw crossbar to Jbox, wire as per local electrical code.
2. Screw fixture to crossbar using threaded nipple and hex nut provided.
3. Place shade into fixture shade ring.

Note: Continuous Circuit -
Either supply wire can connect to white covered wire.

★WARNING★

DO NOT TOUCH BULB WITH BARE FINGERS. FINGER OILS MAY CAUSE BULB TO OVER HEAT AND BURN OUT PREMATURELY.



"A Commitment to Excellence in Lighting and Service"



CALL OUR CUSTOMER SERVICE DEPARTMENT AT 1-800-222-4009

MONDAY - FRIDAY 8:00 a.m. - 6:00 p.m. ET

visit us on the web at www.meyda.com

CUT SHEET, ITEM # 107530

LT603



Item# 107530	Voltage 120	Drawn by ARS
Date 2/9/09	Lenz: Glass	Approval
	#Bulbs 1-GU24 26 watt	Finish IRON/RUST

